

~~10/1/78~~
5/015/046

DCGM RECEIVED
3-28-96



- A. Short access road just west and paralleling the portal access and is not included in Tom Clark's notice, UTU-69856 in T.22S., R.6E., Section 26.



- B. Upper portion of the unapproved access road leading to an unapproved tank, Tom Clark, UTU-69856 in T.22S., R.6E., Section 26. 3-21-96.

~~1-11-96~~

5/015/046

DCGM RECEIVED
3-28-96



C. Tank not included in Tom Clark's notice, UTU-69856, in T.22S., R.6E., Section 26. 3-21-96.



D. Stockpile area north of the new portal, Tom Clark, Notice, UTU-69856, in T.22S., R.6E., Section 26. 3-21-96.

9/019/046

DOGM RECEIVED
3-28-96



E. Looking south at Tom Clark's new portal, notice, UTU-69856 in T.22S., R.6E., Section 26. 3-21-96.



F. Closeup of portal, Tom Clark, notice, UTU-69856 in T.22S., R.6E., Section 26. 3-21-96.

S/019/046

DOGM RECEIVED
3-28-96



G. Compressor located just north of the portal, Tom Clark, Notice,
UTU-69856 in T.22S., R.6E., Section 26. 3-21-96.